




UNDER CONSTRUCTION

Allegan District Library Expansion



Phase I (House Move & Library Addition) 18% Complete



Green's Block and Brick – West Side



Green's Block – South Side



Excavation for Library South Retaining Wall



Site View from South

Work Completed

- Auger cast pile shoring at library

Work in Progress

- Excavation and grading for library addition

Upcoming Work

- Concrete foundations for library addition
- Relocation of overhead Charter lines
- Underground plumbing at Green's
- Replacement of rotted timber at Green's
- Masonry at Green's
- Interior steel at Green's



UNDER CONSTRUCTION

Alleghen District Library Expansion



Shoring/Bracing at Library Addition



Green's House



Existing Retaining Wall Cut to Below New Grade



Green's Bilco Door Location



Partial Backfill at Green's



Partial Backfill at Green's



South Retaining Wall Excavation